

# Webex Carrier Device Firmware Maintenance

## Yealink T5xW v86 Firmware Release

<b>Service Platforms:</b>	<b>Webex Carrier</b>
<b>Markets:</b>	<b>US, EMEA, APAC, Canada</b>
<b>Maintenance Window:</b>	<ul style="list-style-type: none"><li>• <b>US ET: Jan 18, 2022 10:00:00 PM</b></li><li>• <b>CA ET: Jan 18, 2022 10:00:00 PM</b></li><li>• <b>AU AEST: Jan 19, 2022 09:30:00 PM</b></li><li>• <b>EU GMT: Jan 20, 2022 10:30:00 PM</b></li><li>• <b>EUN GMT: Jan 20, 2022 10:30:00 PM</b></li></ul>
<b>Information:</b>	Yealink T5xW upgrade from V85 to V86 firmware
<b>Affected Models:</b>	Yealink T5xW series T53W T54W T57W
<b>What's Changing:</b>	Yealink upgrade from V85 to V86 firmware
<b>Upgrade Details:</b>	<ol style="list-style-type: none"><li>1. Firmware for "Yealink T5xW" device profile will be uploaded and the tags will be changed as below.  APP_VERSION_T53W — 96.86.0.56 APP_VERSION_T54W — 96.86.0.56 APP_VERSION_T57W — 96.86.0.56</li><li>2. The new Ringing functionality will be controlled via new tag "RINGER_DEVICE" The tag will be part of Yealink_PerCountry Tag set Values are as below:  - 0 Use Speaker. Default setting and behavior - 1 Use Headset. -2 Use Headset and Speaker</li></ol>

	<p>3. Yealink support for the new IdenTrust CA which is required by BCLD/Cisco.</p> <p>4. Yealink has fixed security vulnerability issue for T5xW devices</p> <p>WxC Carrier Yealink T5xW would need to be manually resync'd or restarted to force an upgrade to the new firmware.</p>
<b>End User Requirements:</b>	<b>WxC Carrier</b> - Devices should be rebooted after the maintenance activity date.
<b>Documentation</b>	<b>For Yealink v86 Release Notes,</b> <a href="https://support.yealink.com/">https://support.yealink.com/</a>