## **Cisco MPP Firmware Maintenance**

Cisco MPP Firmware Upgrade - Release 12.0.1

| Service Platforms:         | Webex Carrier   |
|----------------------------|---|
| Markets:                   |   |
|                            | NAMER, CANADA, EMEA, APAC   |
| <b>Maintenance Window:</b> | CANADA - <b>CA CDT</b> : 20:00 07 February 2023                                   |
| 12.0.1 Firmware            | EMEA - <b>GMT:</b> 20:00 07 February 2023   |
| Upgrade                    | •   |
|                            | NAMER - <b>US ET:</b> 20:00 07 February 2023                                      |
|                            | APAC - <b>AEST</b> : 20:00 07 February 2023                                       |
| Information:               | 1   |
| Affected Models:           | Cisco MPP 6800, 7800, and 8800 Series   |
| What's Changing:           | MPP Firmware Upgrade 11.3.7SR1> 12.0.1  |
| Upgrade Details:           |   |
|                            | Fixes   |
|                            | • CSCwa95349: Cloud awareness: Phone will create new                              |
|                            | registration after reboot or for each refresh request                             |
|                            | • CSCwb84477: 8865: KEM Type is set to unsupported                                |
|                            | option, phone will not report kem "offline" status to cloud                       |
|                            | • CSCwb85883: 88xx 88x5 the generated PRT toast content                           |
|                            | will overlap when a paging call is received                                       |
|                            | • CSCwc08931: Cisco MPP 8851 IP Phone with Cisco 561                              |
|                            | USB headset are randomly crashing   |
|                            | • CSCwc29314: MPP phones (88xx/68xx/78xx) do not                                  |
|                            | support dual registration with TCP  |
|                            | • CSCwd47209: The 'ACK' from MPP phone does not have                              |
|                            | 'Route' header.   |
|                            | CSCwd56139: Cisco MPP phones "Debug" level log still                              |
|                            | print out when log level set to "Notice"  |
|                            | _   |
|                            | <ul> <li>CSCwd62034: AWR-WB Media Type does not conform to<br/>RFC4867</li> </ul> |
|                            | CSCwd62809: Intermittent audio noises are heard on                                |
|                            | Webex calls   |
|                            | TTODEN GUID   |

| End User Requirements: | <ul> <li>CSCwd01853: Cisco MPP Phones reboots when park and retrieve a call too fast</li> <li>CSCwb65913: ICE: Phone crashes when STUN server is not reachable due to port block</li> <li>CSCwd93487: 8851 KEM Memory leak causing reboot</li> <li>CSCwc61284: SSH is not available for phones running Multiplatform Phone (MPP) firmware</li> <li>Devices should be rebooted after the maintenance activity date.</li> </ul> |
|------------------------|---|
| Documentation          | <ul> <li>MPP Release Notes</li> <li>6800 Release Notes</li> <li>7800 Release Notes</li> <li>8800 Release Notes</li> </ul>   |