Cisco WxC Carrier Firewall Requirement Change

Cisco MPP Firmware Location Change

Service Platforms:	**Webex Calling Carrier**
Markets:	**NAMER, CANADA, EMEA, APAC**
Information:	Cisco MPP Firmware Binary Location
Affected Models:	Cisco MPPs
What's Changing:	Cisco MPP firmware locations will change to use the location URL of https://binaries.webex.com
Upgrade Details:	• Beginning in mid-September, all the Cisco MPP Firmware will transition to use https://binaries.webex.com as the host URL for MPP firmware upgrades in all regions. • This change is being made to improve firmware upgrade performance.
End User Requirements:	**WxC Carrier –** Customers should open up this new URL on their firewalls. Please inform and ensure your customers are allowing the new URL. These are AWS severs and our recommendation is to allow the URL and not IP addresses associated with it as they can change over time.
Documentation	Latest Firewall guide is posted here