Cisco WxC Carrier CPE Announcement

Yealink T33G, T4xS and T4xU Firmware Upgrade to Support RedSky Emergency Calling

Service Platforms:	**Webex Calling Carrier**
Markets:	NAMER
Maintenance Window:	**NAMER** - US ET: 25/July/2022 - 10:00 PM
Information:	Yealink models T53W, T54W and T57W should be upgraded with the latest firmware (v86 96.86.0.109) version to fix a device issue causing these models to potentially become unresponsive
Affected Models:	• T53W • T54W • T57W
What's Changing:	The above Yealink models will have their firmware upgraded to the following v86 version: • 96.86.0.109
New Features:	1. None.
Bug Fixes	Fixed bug causing the T5xW's to potentially become unresponsive
End User Requirements	**Webex Calling Carrier** - End Users must resync or manually reboot their T53W, T54W and T57W IP Phones to prompt the upgrade.
Release Notes	**For Yealink v84 and v86 Release Notes, please click the following link:** https://support.yealink.com/