Webex Carrier Device Firmware Maintenance

Yealink W60B v85 Firmware Release

Service Platforms:	**Webex Carrier**
Markets:	**US, EMEA, APAC, Canada**
Maintenance Window:	EMEA - **GMT: 8/July/21 09:00:00 PM** CA - **CA EST: 9/July/21 09:30:00 PM** APAC - **AEST: 12/July/21 09:00:00 PM** US - **US EST: 13/July/21 08:00:00 PM**
Information:	Yealink W60B upgrade from V83 to V85 firmware
Affected Models:	Yealink W60B Series
What's Changing:	Yealink upgrade from V83 to V85 firmware to support new W60B hardware
Upgrade Details:	1. Yealink has introduced new hardware chip in their new W60 base which requires new firmware for interworking for both versions of hardware 2. Yealink W60B will now support new W59R handset 3. Yealink support the new IdenTrust Certificate Authority required by Cisco SERVICE IMPACT: WxC Carrier Yealink W60 base stations would need to be manually resync'd or restarted to force an upgrade to the new firmware.
End User Requirements:	**WxC Carrier** - Devices should be rebooted after the maintenance activity date.
Documentation	**For Yealink v85 Release Notes,** https://support.yealink.com/