

Cisco WxC Carrier CPE Announcement

“Yealink T5xW and T4xU” IP Phone Firmware Upgrade

Service Platforms:	Webex Calling Carrier
Markets:	APAC, EU, EUN, US, CA
Maintenance Window:	APAC – 10 PM AEDT, November 10, 2023 EU – 10 PM GMT, November 13, 2023 EUN – 11 PM CET, November 13, 2023 US – 10 PM EDT, November 14, 2023 CA – 11 PM EDT, November 14, 2023
Information:	“Yealink T5xW and T4xU” firmware upgrade to latest FW <ul style="list-style-type: none">• 108.86.0.142 for T4xU• 96.86.0.142 for T5xW
Affected Models:	Yealink models T5xW and T4xU
What’s Changing:	APP_VERSION_T4xU -> 108.86.0.142 APP_VERSION_T5xW-> 96.86.0.142
Upgrade Reasons:	Fixes the port issue when connecting to EXP50 (UI will stuck at “Welcome”). Yealink has rolled out 108.86.0.142 for T4xU and 96.86.0.142 for T5xW.
End User Requirements	WxC Carrier Yealink T5xW and T4xU phones would need to be manually restarted to force an upgrade to the new firmware.
Documentation	For Yealink T5xW and T4xU Release Notes, <ul style="list-style-type: none">• https://support.yealink.com/

