

# Cisco MPP Firmware Maintenance

## Cisco MPP Firmware Upgrade - Release 11.3.7SR1

<b>Service Platforms:</b>	<b>Webex Carrier</b>
<b>Markets:</b>	<b>NAMER, CANADA, EMEA, APAC</b>
<b>Maintenance Window: 11.3.7 SR1 Firmware Upgrade</b>	CANADA - CA CDT: 7/Nov/22 09:00:00 PM EMEA - GMT: 7 and 8/Nov/22 07:00:00 PM EUN - GMT: 7/Nov/22 08:00:00 PM NAMER - US ET: 7 to 17/Nov/22 08:00:00 PM APAC - AEST: 7 and 8/Nov/22 08:00:00 PM **Note NAMER customers will be upgraded over that window
<b>Information:</b>	Cisco MPP Firmware Upgrade to 11.3.7SR1
<b>Affected Models:</b>	Cisco MPP 6800, 7800, and 8800 Series
<b>What's Changing:</b>	MPP Firmware Upgrade 11.3.7 → 11.3.7SR1
<b>Upgrade Details:</b>	<p>Following defects have been fixed in this new release</p> <p>CSCwb65913: ICE: Phone crashes when STUN server is not reachable due to port block</p> <p>CSCwc75949: 8832 intermittently mutes and unmutes the microphone without user intervention</p> <p>PSIRT-0679991334/CSCwc78400: Command injection during PRT file generation</p> <p>PSIRT-0679991334/CSCwc78413      Stored XSS via packet capture filename</p> <p>PSIRT-0679991334/CSCwc78427      Secure data partition is world readable and writable</p> <p>PSIRT-0679991334/CSCwc78405      Privilege escalation to root user via continually executing script</p> <p>CSCwb65732: Camera LED is still on after hang up the video call</p> <p>CSCwb92297: 78xx VID 20 E2M, then back to E fail</p>

	<p>CSCwc08931: Cisco 8851 MPP Phone with Cisco 561 USB headset is randomly crashing</p> <p>CSCwc54182: When sending an activation request, stop retries after a number of failures</p>
<b>End User Requirements:</b>	<b>WxC Carrier</b> - Devices should be rebooted after the maintenance activity date.
<b>Documentation</b>	<p><b>MPP Release Notes</b></p> <ul style="list-style-type: none"> <li>• <a href="#">6800 Release Notes</a></li> <li>• <a href="#">7800 Release Notes</a></li> <li>• <a href="#">8800 Release Notes</a></li> </ul>