## **Cisco DECT Endpoint Maintenance**

## **Cisco DECT Firmware Upgrade to v480B20**

Service Platforms:	Webex Carrier
Markets:	US, EMEA, APAC, Canada
Maintenance Window:	CANADA - CA CDT: 3/Aug/21 08:00:00 PM  EMEA - GMT: 4/Aug/21 08:00:00 PM  NAMER - US ET: 5/Aug/21 09:00:00 PM  APAC - AEST: 4/Aug/21 11:00:00 PM
Information:	Firmware upgrade for Cisco DECT DBS-210
Affected Models:	Cisco DECT DBS-210 Base (v480 already deployed for DBS-110)
What's Changing:	MPP DECT Firmware Upgrade from v470B8 to v480B20

Change Details:	Firmware update from 470B8 to 480B20:
	<ol> <li>Support for the Cisco IP DECT 6823 handset</li> <li>Support for Cisco IP DECT RPT-110 Repeater         <ul> <li>a. The Repeater extends the connectivity range of handsets registered to the Base Stations. The Deployment Guide provides more detail on how combinations of Base Stations and Repeaters may be installed to satisfy different signaling coverage scenarios.</li> </ul> </li> <li>Temporary Multicell Feature for Calling         <ul> <li>a. This short term multicell solution requires manual intervention to complete. The solution is valid for up to 5 base stations and 30 handsets. A TAC Service Request is required to provide assistance in configuring this solution</li> </ul> </li> <li>Firmware requirement to upgrade to the full Multicell Solution</li> </ol>
End User Requirements:	<b>WxC Carrier</b> – Customers / Users will need to re-sync or reboot their base stations in order to trigger the upgrade.
Documentation:	Cisco DECT Firmware Release Notes  https://www.cisco.com/c/en/us/support/collaboration- endpoints/ip-dect-6800-series-multiplatform-firmware/products- release-notes-list.html