

Cisco MPP Firmware Maintenance

Cisco MPP Firmware Upgrade - Release 11.3.7SR1

Service Platforms:	Webex Calling Carrier
Markets:	NAMER, CANADA, EMEA, APAC
Maintenance Window: 11.3.7 SR1 Firmware Upgrade	CANADA - CA CDT: 14/Nov/22 09:00:00 PM EMEA - GMT: 14/Nov/22 08:00:00 PM EUN - GMT: 14/Nov/ 22 09:00:00 PM NAMER - US ET: 14/Nov/22 08:00:00 PM APAC - AEST:14/ Nov/ 22 08:00:00 PM **Note NAMER customers will be upgraded over that window
Information:	Cisco MPP Firmware Upgrade to 11.3.7SR1
Affected Models:	Cisco MPP 6800, 7800, and 8800 Series
What's Changing:	MPP Firmware Upgrade 11.3.7 → 11.3.7SR1
Upgrade Details:	<p>Following defects have been fixed in this new release</p> <p>CSCwb65913: ICE: Phone crashes when STUN server is not reachable due to port block</p> <p>CSCwc75949: 8832 intermittently mutes and unmutes the microphone without user intervention</p> <p>PSIRT-0679991334/CSCwc78400: Command injection during PRT file generation</p> <p>PSIRT-0679991334/CSCwc78413 Stored XSS via packet capture filename</p> <p>PSIRT-0679991334/CSCwc78427 Secure data partition is world readable and writable</p> <p>PSIRT-0679991334/CSCwc78405 Privilege escalation to root user via continually executing script</p> <p>CSCwb65732: Camera LED is still on after hang up the video call</p> <p>CSCwb92297: 78xx VID 20 E2M, then back to E fail</p>

	<p>CSCwc08931: Cisco 8851 MPP Phone with Cisco 561 USB headset is randomly crashing</p> <p>CSCwc54182: When sending an activation request, stop retries after a number of failures</p>
End User Requirements:	WxC Carrier - Devices should be rebooted after the maintenance activity date.
Documentation	<p>MPP Release Notes</p> <ul style="list-style-type: none"> • 6800 Release Notes • 7800 Release Notes • 8800 Release Notes